

Union Station – Train Separation Event October 9, 2020

Preliminary Investigation
Briefing
October 22, 2020



Executive Summary


- Train 108 separated upon departure from Union Station on October 9, 2020
- No initial injuries reported
- Two passengers treated on scene for chest pains/ shortness of breath
- Human factors remain under review as part of ongoing investigation
- Information contained within this brief should be considered preliminary and subject to change as the investigation proceeds

Incident Summary


- Red Line Train 108 (6K Series) experienced a separation between cars 2 and 3 while in service upon departure from Union Station, on track #1, approximately 12:18 PM, on October 9, 2020
- Upon uncoupling, the emergency braking system activated (brake pipes dump followed by emergency brake relay de-energized), Train 108 stopped after traveling 172ft after train length changed from eight to two cars
- DCFD, MTPD, SAFE, RTRA responded; all external parties notified
- Investigation underway:
 - Vehicle inspections and testing
 - Employee and responder interviews
 - Data reviews
 - event recorders
 - maintenance records
 - training records
 - CCTV



General Overview



Railcar Placement Overview



 - Represents 1-married pair. Total of eight cars

Involved Equipment Photographs



Car 6079 Front Coupler assembly coupled to half of car 6075 Front Coupler



Car 6075 Front Mechanical Coupler Draft Bar



Close up of Car 6079 Front Coupler assembly coupled to half of car 6075 Front Coupler



Car 6075 Front Mechanical Coupler Buffer Tube






Photo of Draft Gear

Incident Chronology

**Note that times are approximate and subject to additional refinement as the investigation matures*



Initial Investigation Findings


VMS Railcar Data Downloads

- Data does not show any abnormalities with train operations that could result in this incident

Office of Car Maintenance

- As a result of this event, CMNT conducted a rail car inspection of all couplers on the 6k series
 - Total railcars inspected: 166 (90% of the 6K fleet, remaining 18 removed from service until inspected)
 - Six railcars identified with potential discrepancies with three cars having incorrect hardware installed
 - The coupler was replaced on November 2019
 - Typical coupler overhaul is eight years
 - The railcar underwent several inspections (including coupler inspections, on January 16, April 22, June 16, August 21) leading up to the pull-apart event
 - Inspections did not identify any discrepancies with the coupler
- Based on mileage data, the impacted traveled 35,522 miles since the coupler replacement and before the subsequent separation

Event Recorder (ER) Data Graph/Sequence of Events




Historical Decoupling Event

- Similar event occur outside of McLean station on August 25, 2018
- An incorrect bolt was used which provided a false torque reading resulting in reduced clamping force on the buffer tube, which in-turn allowed the spanner nut to slowly back out over time
- Mitigation included development of Maintenance Service Inspection (MSI-150088) outlining rebuild procedures for 6K Semi-Permanent Drawbars and any other action deemed necessary to support prevention of repeated pull apart event
- A fleet wide inspection was conducted for immediate mitigation purposes

The investigation will determine the relationship between the current and prior events

Incident Investigation Chronology Reconstruction

Note that timeline is developed from eye witness accounts and employee interviews



Torque Explained

What is torque?

- Application of a force acting at a radial distance and tending to cause rotation, and is used to create tension

Why?

- The tension in the bolt creates a "clamping" force between the two parts
- If the clamping force is too low, the fasteners can work loose due to vibration or movement between the component parts
- If a clamping force is too high, the fastener may permanently stretch and no longer apply the required clamping force

What is a torque stripe?

Torque stripe is used as a visual indicator to mark fasteners that have been torqued to make it obvious if it becomes loose



Torque stripe when the buffer tube was installed in car 6075



Torque stripe when the buffer tube was delivered to the MRO Shop

- The investigation into the chain of custody and investigation process adherence revealed multiple gaps in understanding of roles, responsibilities and protocols surrounding incident investigations
- The current process details expectations for investigators and has general information about evidence preservation
 - 800-01: Incident and Accident Investigations of RAIL, BUS and MetroAccess

“For all incidents ... involving rail vehicles, CENV, CMNT and CTEM must obtain written release of the equipment via email or verbal notification from SAFE’s Deputy Chief, Investigations or his/her designee before VMS/Event Recorder downloads, or any type of inspection activity, commences on or around the rail vehicle”
- Access controls for quarantined evidence and formal documentation of chain of custody are not part of the existing process

- Existing incident investigation training for employees focuses on the investigator's role
- Employees who may be part of an investigation do not receive any training on their role in support of the investigation
- Metro is undertaking a comprehensive reevaluation of the investigation process to identify further opportunities to improve the structure of protocols
- This evaluation will apply lessons learned from prior investigations and will clarify expectations for involved parties and establish accountability for execution of the process

- Complete Fact-Finding
 - Additional interviews with involved staff
 - Complete records reviews and data fusion
 - Final damage assessments
 - Laboratory and engineering reports are pending
 - Investigating nonconforming materials (e.g., bolts)
 - Investigating the potential of improper preventative maintenance on a front coupler resulting in improper torque value
- Conduct further analysis
 - Identify any commonalities between prior decoupling events
 - Ensure mitigations/corrective actions from prior events are sustainable
- Initiate immediate actions and develop corrective action plans to address the incident causal factors
- Identify and implement investigation protocol improvements
- Complete draft report, submit to WMSC