

## **Washington Metropolitan Area Transit Authority (WMATA)**

National Transportation Safety Board (NTSB) Tracker As of 08/15/25

	Corrective Action Pla	an (CAP) Summary	
Total	Submit	Onon (a)	
	Closed	Under Review <sup>1</sup>	Open (•)
32	26	4	2

<sup>&</sup>lt;sup>1</sup> Under Review status includes items that were submitted to NTSB for review and closure, and items that were returned by NTSB to address additional comments.

Risk Assessment Category and Description						
I	II	III	IV			
Unacceptable	Undesirable - ESC* Decision Required	Acceptable with ESC* Review	Acceptable without ESC* Review			
Submitted: 0   Open: 1	Submitted: 16   Open: 1	Submitted: 10   Open: 0	Submitted: 4   Open: 0			

<sup>\*</sup> ESC - Executive Safety Committee

CAP Number	Risk Assessment	Closure Submission Date**	CAP Status	Actionable Item Status
------------	--------------------	---------------------------------	------------	------------------------

<sup>\*\*</sup>Date WMATA requests closure. Actual closure date is subject to WMSC review and acceptance of the closure.

Railroad and Rail Tra	nsit Roadway \	Worker Protection		0%	1 50%	100%	100%
NTSB-R-08-004	1	December 2022	Open				100%
√ WMATA implemented a	ppropriate technolo	gy to notify wayside worke	ers of approaching t	trains and train oper	ators when approaching areas with workers o	on or near the track	S.

llision of Two W	MATA Trains Ne	ar Fort Totten Statio	on				100%
				0%	50%	100%	
NTSB-R-10-20	II	September 2017	Closed				100%
WMATA removed 10	00-series railcars from	service as new 7000-series	railcars were comm	issioned and placed in	-service.		
NTSB-R-10-21	II	December 2015	Closed				100%
WMATA equipped le	ad railcar pairs with an	operating onboard event	recorder.				
		June 2016	Closed				100%
NTSB-R-10-22	III						



Closure Risk **Actionable Item Status CAP Number Submission CAP Status Assessment** Date\*\* \*\*Date WMATA requests closure. Actual closure date is subject to WMSC review and acceptance of the closure. WMATA L'Enfant Plaza Station Electrical Arcing and Smoke Accident -98% Safety Recommendations from the Accident Final Report NTSB-R-16-08 April 2022 100% Closed Review and revise WMATA's tunnel inspection, maintenance, and repair procedures to mitigate water intrusion into tunnels. WMATA developed maintenance/inspection procedures to identify and mitigate water intrusion into the tunnels. WMATA confirmed there is reasonable evidence to support completion of actionable items and performance measures. NTSB-R-16-09 June 2024 **Under Review** 100% When the revision of tunnel inspection, maintenance, and repair procedures recommended in Safety Recommendation R-16-08 have been completed, train maintenance employees on the new procedures, and ensure that the procedures are implemented. WMATA developed maintenance/inspection procedures to identify and mitigate water intrusion into the tunnels. WMATA incorporated a revised tunnel inspection, maintenance, and repair procedures into training curriculum. WMATA rolled out a new curriculum and training program. WMATA created an audit plan and schedule to verify implementation. WMATA confirmed there is reasonable evidence to support completion of actionable items and performance measures. NTSB-R-16-10 July 2018 Ш 100% Closed Improve the capacity of tunnel ventilation fans to conform to the requirements of National Fire Protection Association (NFPA) 130. WMATA reviewed existing ventilation studies that have been completed and also developed a recommended approach to analyzing the entire underground ventilation system for compliance with NFPA 130. WMATA issued a contract for ventilation analysis. WMATA recommended infrastructure improvements. WMATA developed an action plan for recommended improvements. Finally, WMATA performed a quality assurance audit to review actionable items. NTSB-R-16-11 September 2017 Closed 100% Develop and implement procedures for actions to be taken by Rail Operations Control Center (ROCC) personnel when smoke detectors alarm. WMATA wrote tunnel ventilation procedures in conjunction with NTSB R-15-9. WMATA analyzed potential tunnel ventilation system improvements. WMATA developed location-specific emergency ventilation configurations. Finally, WMATA performed a quality assurance audit to review actionable items. NTSB-R-16-12 September 2019 Closed 100% Develop location-specific emergency ventilation config based on engineering studies of the WMATA tunnel ventilation system. WMATA wrote tunnel ventilation procedures in conjunction with NTSB R-15-9. WMATA set a specific set of steps and responsibilities for smoke detector alarms. Finally, WMATA performed a quality assurance audit to review actionable items. NTSB-R-16-13 Ш March 2020 Closed 100% Once action to address Safety Recommendation R-16-12 is completed, train all ROCC personnel on the new procedures for responding to smoke alarms. This training should include regular refresher training. WMATA developed and implementing procedures for actions to be taken by ROCC personnel when smoke detectors alarm. WMATA incorporated procedures into the ROCC curriculum, to include refresher training. WMATA provided documentation of training. Finally, WMATA performed a quality assurance audit to review actionable items. NTSB-R-16-14 December 2016 100% Closed Incorporate smoke alarms in periodic emergency drills and exercises. WMATA conducted quarterly emergency drills. WMATA developed a drill and coordination plan for the drill scheduled for October 2016. Finally, WMATA performed a quality assurance audit to review actionable items. NTSB-R-16-15 Ш May 2018 Closed 100% Include in your efficiency testing program (rules compliance testing program) a specific test to ensure appropriate emergency actions are taken by ROCC supervisors and control operators in response to an alarm. WMATA conducted efficiency testing. WMATA conducted specific tests for ROCC personnels' response to alarms. Finally, WMATA performed a quality assurance audit to review actionable items. NTSB-R-16-16 August 2020 Open 33% Install and maintain a system that will detect the presence and location of fire and smoke throughout the WMATA tunnel and station network. WMATA evaluated and tested potential smoke detection solutions. WMATA will develop an implementation plan for selected smoke detection solution. WMATA will confirm there is reasonable evidence to support completion of actionable items and performance measures.

CAP Number	Risk Assessment	Closure Submission Date**	CAP Status	Actionable Item Status	
**Date WMATA requests closu	re. Actual closure da	ate is subject to WMSC rev	iew and acceptance of	the closure.	
NTSB-R-16-17	III	April 2020	Under Review		100%
Develop procedures for regula	<del>-</del>				
<ul><li>✓ WMATA developed prod</li><li>✓ WMATA confirmed there</li></ul>		*	tion of actionable item:	s and performance measures.	
NTSB-R-16-18	III	February 2019	Closed		100%
Conduct a risk assessment bef  √ WMATA revised System	= -	· =	_	discontinued. sintenance procedures are subject to formal approval.	
· ·	. , ,		,	ures that are subject to formal approval.	
√ WMATA reviewed existin	• .				
•	•	ate that changes in preven nce audit to review actiona	·	cedures must be approved as described.	
NTSB-R-16-19	III	June 2017	Closed		100%
Ensure that all train operators	are trained and re	gularly tested on the appr	opriate procedure for	emergency shutdown of railcar ventilation.	
√ WMATA updated the pe	•				
<ul><li>√ WMATA updated the ne</li><li>√ WMATA confirmed there</li></ul>		-	tion of actionable item:	s and performance measures.	
	ı				
NTSB-R-16-20	III	February 2017	Closed		100%
Incorporate a specific test in y	our efficiency testir	ng program to ensure tha	t train operators unde	rstand the procedure for emergency shutdown of railcar ventilation.	
√ WMATA implemented a		-			
'	<u> </u>	y shutdown of railcar venti vidence to support comple		s and performance measures.	
NTSB-R-16-21	IV	June 2017	Closed		100%
Revise Standard Operating Pro	ı ocedure (SOP) #6 t	o clarify which trains shou	ıld be stopped until th	e source of smoke is identified.	
· ·		that must be stopped in th		ident.	
v Finally, WMATA perform	ed a quality assurar	nce audit to review actiona	ble items.		
NTSB-R-16-22	IV	October 2017	Closed		100%
Revise vour SOP to require th	at: (1) suitably train	ed qualified and properly	/ equipped personnel	investigate reports of wayside fire or smoke, and (2) these reports are not investi	igated using
trains with revenue passenger	-	ou, quamicu, and properly	, equipped personins.		.gatea asg
√ WMATA created proced					
<ul><li>√ WMATA developed an S</li><li>√ Finally, WMATA perform</li></ul>		sugation. nce audit to review actiona	ble items.		
NTSB-R-16-23	IV	June 2021	Under Review		100%
Review and revise as necessar	y your ROCC emer	gency response procedur	es for smoke and fire.		
· ·	•	edures for Operations Conf	crol Center staff.		
<ul> <li>√ WMATA developed prod</li> <li>√ WMATA developed drills</li> </ul>		r SOPs. esponse to smoke and fire	۵		
· ·		s for ROCC response to fire		ies.	
√ WMATA confirmed there	e was reasonable ev	idence to support comple	tion of actionable item:	s and performance measures.	
NITCD D 16 24		Cantambar 2017	Under Pavierr		1000/
NTSB-R-16-24		September 2017	Under Review		100%
Retrain ROCC supervisors on a √ WMATA established SOF	•		encies.		
√ WMATA retrained ROCC	·				
√ WMATA confirmed there	e was reasonable ev	ridence to support comple	tion of actionable item:	s and performance measures.	
NTSB-R-16-25	II	June 2019	Closed		100%
·			ntrol operators in eme	rgency response procedures including regular refresher training.	
√ WMATA undeted amore					
<ul><li>√ WMATA updated emerg</li><li>√ WMATA developed and</li></ul>	,	ning. edures for smoke detector	alarms.		
√ WMATA trained all ROC	C personnel on the	new procedures for smoke	e detector alarms.		
√ WMATA confirmed there	e is reasonable evid	ence to support completio	n of actionable items a	nd performance measures.	

	CAP Number	Risk Assessment	Closure Submission Date**	CAP Status	Actionable Item Status
**Dat	e WMATA requests closu	re. Actual closure da	ate is subject to WMSC rev	view and acceptance of the	he closure.
	NTSB-R-16-26	II	March 2019	Closed	100%
		esponse drills and o	develop a program to tes	t the efficiency of the RC	DCC to ensure that standard operating procedures are properly followed during
	gencies.		-t		
	WMATA conducted drills		response to smoke & fire.		
√ √			compliance with emergenc	v procodures during drill	
v √	·	,			and performance measures.
V	WWATA committee there	was reasonable ev	riderice to support comple	tion of actionable items	and performance measures.
	NTSB-R-16-27	III	November 2017	Closed	100%
nstal	l line identification and d	irection signage at	tunnel entrances and insi	de tunnels.	·
$\sqrt{}$	WMATA determined app	oropriate signage lo	ocations.		
$\sqrt{}$	WMATA surveyed tunne	ls to map proposed	l locations.		
$\sqrt{}$	WMATA developed prop	oosed improvement	ts and a tentative impleme	entation plan for jurisdicti	onal review.
$\checkmark$	·	•	·	•	accepted by jurisdictional fire chiefs.
$\checkmark$	Finally, WMATA perform	ed a quality assurar	nce audit to review actiona	able items.	
	NTSB-R-16-28	II	March 2023	Closed	100%
mple	ement a regular schedule	for the inspection	and removal of obstruction	ons from safety walkway	s and track-bed floors to ensure safe passageways for passengers to use during a tunnel
vacı	uation.				
$\sqrt{}$	WMATA removed obstru	uctions from safety	walkways.		
$\sqrt{}$					g of obstructions in the roadway and on safety walkways.
$\sqrt{}$	WMATA confirmed there	e is reasonable evid	ence to support completic	on of actionable items an	d performance measures.
	NTSB-R-16-29	II	February 2017	Closed	100%

√ WMATA conducted quarterly emergency drills.

- $\checkmark$  WMATA outlined the standard approach for documenting drills in accordance with industry guidelines.
- √ Finally, WMATA performed a quality assurance audit to review actionable items.

NTSB-R-16-30 IV February 2017 Closed 100%

Revise your standard operating procedures to require that an after-action review be conducted of all emergency responses to events with passenger or employee fatalities, and publish the

Revise your standard operating procedures to require that an after-action review be conducted of all emergency responses to events with passenger or employee fatalities, and publish the results, including both the successes and the potential deficiencies of your responses, to help ensure that deficiencies are appropriately remediated.

- $\lor$  WMATA developed an SOP detailing requirements for performing an After-Action Review (AAR).
- √ Finally, WMATA performed a quality assurance audit to review actionable items.

NTSB-R-16-31 | II | August 2017 | Closed | 100%

Review and revise your quality assurance program to ensure that regular quality assurance audits are included to identify and correct any elements of procedural noncompliance.

- √ WMATA developed an overview of the Quality Management System (QMS), quality objectives and guiding principles.
- √ WMATA reviewed the existing manual and identified gaps.
- $\ensuremath{\checkmark}$   $\ensuremath{\mbox{ WMATA}}$  revised manual to incorporate input from gap analysis.
- $\lor$  WMATA implemented updated QMS.
- WMATA confirmed there was reasonable evidence to support completion of actionable items and performance measures.