

WMATA Solicitation FQ16005/WJG
Structural Retrofit of B9 Beam at Farragut North Metrorail Station
Contractor Questions / WMATA Responses

<u>Question No.</u>	<u>RFP Section</u>	<u>Question</u>	<u>WMATA Response</u>
1		Is there any specific finish/coat for the cladding?	Refer to Volume 2 – Technical Specifications Section 03495-3 PRECAST GLASS FIBER REINFORCED POLYMER CONCRETE PANELS 2.02 G “Finishes: Exposed panel faces to match existing building concrete column elements or approved samples. Joint marks, grain, or other obvious defects on panel faces are not acceptable.
2		Can Safety Superintendent and First Aid Attendant be the same full time person?	Yes. Refer to Amendment No. 2.
3		Does the Safety Superintend need to be present at all times if the First Aid Attendant is on site?	Yes. Refer to Amendment No. 2.
4		This is a small project and staffed with two full time Safety professionals, can WMATA re-consider this requirement and eliminate one or the other?	Yes. Refer to Amendment No. 2.
5		Can the Construction General Superintendent act as the Safety Superintendent full-time?	Yes. Refer to Amendment No. 2.