ARCHITECTURAL KEYNOTES

KEYED NOTES BY DEFICIENCY

1- CORROSION

- CORROSION ON DOOR, REPLACE IN KIND.
- $\langle 1B \rangle$ CORROSION ON DOOR FRAME, REPLACE. SEE DETAIL 1 ON DWG. K06-A-502
- $\langle 1C \rangle$ corrosion on door closer. Replace in kind.
- CORROSION ON BOLLARD. SCRAPE CLEAN, PRIME, AND REPAINT TO MATCH EXISTING.
- CORROSION ON PIPE GUARD. SCRAPE CLEAN, PRIME, AND REPAINT TO MATCH EXISTING.
- \langle 1Fangle CORROSION ON HANDRAIL. SCRAPE CLEAN, PRIME, AND REPAINT TO MATCH EXISTING.
- CORROSION ON GUARDRAIL. SCRAPE CLEAN, PRIME, AND REPAINT TO MATCH EXISTING.
- CORROSION ON FENCING/ LIGHTWALL FENCING. SCRAPE CLEAN, AND TREAT WITH ANTI-CORROSIVE.
- CORROSION ON RAMP EDGE. SCRAPE CLEAN AND TREAT WITH ANTI-CORROSIVE.
- $\langle {
 m 1J}
 angle$ corrosion on sign post. Scrape clean, prime, and repaint to match existing.
- CORROSION ON STOREFRONT MULLIONS. SCRAPE CLEAN AND FINISH TO MATCH EXISTING.
- CORROSION ON GATE BOOTH. SCRAPE CLEAN, PRIME, AND REPAINT.
- $\langle 1M \rangle$ CORROSION ON FLASHING. REPLACE. SEE DETAIL 3 ON DWG. K06-A-503.
- (1N) CORROSION ON CEILING TRIM. REPLACE IN KIND.

2 - IMPACT DAMAGE/ DISLODGED/ MISALIGNED

- MISALIGNED EXIT GATE. RESET.
- DISLODGED/MISALIGNED SIGNPOST. REPLACE IN KIND. SEE DETAIL 4 ON DWG. K06-A-502
- DAMAGED/ MISALIGNED DOOR. REPLACE IN KIND.
- DAMAGED/ MISALIGNED DOOR CLOSER. REPLACE IN KIND.
- DISLODGED WHEEL STOP. REPOSITION TO PROPER LOCATION.
- IMPACT DAMAGE TO FLASHING. REPLACE IN KIND. SEE DETAIL 3 ON DWG. K06-A-502.
- DISLODGED/ MISALIGNED HANGING SIGN. REPLACE IN KIND. SEE DETAIL 1&2 ON DWG. K06-A-503.
- (2H) MISALIGNED THRESHOLD. REPLACE IN KIND. SEE SILL DETAIL 1&2 ON DWG. K06-A-502.

3 - DETACHED/ DAMAGED

- DETACHED STOREFRONT MULLIONS. REATTACH.
- DAMAGED CHAIN LINK FENCE. REPLACE IN KIND. SEE DETAIL 3 ON DWG. K06-A-503.
- DETACHED/MISSING TENSION BAR. REPLACE IN KIND. SEE DETAIL 2 ON DWG. K06-A-503.
- DETACHED STAIR NOSING. REPLACE IN KIND. SEE STRUCTURAL DRAWING.

4 - CHIPPED/ PEELED PAINT ON ELEMENTS

- (4A) CHIPPED/ PEELED PAINT ON BOLLARD. SCRAPE CLEAN, PRIME, REPAINT TO MATCH EXISTING.
- CHIPPED/ PEELED PAINT ON PIPE GUARD. SCRAPE CLEAN, PRIME, REPAINT REPAINT TO MATCH EXISTING.
- CHIPPED/ PEELED PAINT ON HANDRAIL. SCRAPE CLEAN, PRIME, REPAINT REPAINT TO MATCH EXISTING.
- CHIPPED/ PEELED PAINT ON GUARDRAIL. SCRAPE CLEAN, PRIME, REPAINT REPAINT TO MATCH EXISTING.
- CHIPPED/ PEELED PAINT ON FIRE PROTECTION PIPE. SCRAPE CLEAN, PRIME, REPAINT REPAINT TO MATCH EXISTING.
- CHIPPED/ PEELED PAINT ON WALLS. SCRAPE CLEAN, PRIME, REPAINT REPAINT TO MATCH EXISTING.
- CHIPPED/ PEELED PAINT ON CLEARANCE BAR. SCRAPE CLEAN, PRIME, REPAINT REPAINT TO MATCH EXISTING.
- $\langle 4H \rangle$ CHIPPED/ PEELED PAINT ON LIGHTWALL BAR. SCRAPE CLEAN, PRIME, REPAINT REPAINT TO MATCH EXISTING.

5 - FADED/ SCRATCHED PAINT ON SURFACES

- $\langle 5A \rangle$ FADED OR MISSING PAVEMENT STOP BAR. REPAINT ALL. SEE DETAIL 1 ON DWG. A12-A-504.
- (5B) FADED OR DOUBLE ADA PAVEMENT MARKING. (REPAINT ALL.) SEE DETAIL 2 ON DWG. A12-A-504.
- (5C) FADED OR DOUBLE PARKING STRIPE. (RĚPĂIŇT ALL.) SEE DETAIL 3 ON DWG. A12—A—504.
- FADED NO PARKING STRIPING (REPAINT ALL TO MATCH EXISTING. 1
- FADED OR UNREADABLE SIGN. REPLACE IN KIND
- FADED OR MISSING PAVEMENT ARROWS. $\{REPAINT ALL.\}$ SEE DETAIL 4 ON DWG. A12-A-504.
- \langle 5Gangle faded or scratched curb paint. \langle repaint all \langle to match existing.
- FADED CROSSWALK. REPAINT ALL TO MATCH EXISTING.

6 - DAMAGED SEALANT

- DAMAGED SEALANT. SCRAPE CLEAN REPLACE IN KIND.
- DETACHED WEATHER STRIPPING. REINSTALL.

7 - MISSING ELEMENTS

- MISSING ACOUSTICAL CEILING TILES. REPLACE. SEE DETAIL 4 ON DWG. A12-A-503.
- MISSING SIGN. REPLACE IN KIND.
- (7C) MISSING/DAMAGED HARDWARE. REPLACE IN KIND. SEE DOOR SCHEDULE, DWG. A12-A-501.
- MISSING SCREWS/BOLTS. REPLACE IN KIND.
- MISSING KICKPLATE. REPLACE IN KIND.
- MISSING OR DETACHED SAFETY STRIP. REPLACE IN KIND.
- MISSING WALL TILES. REPLACE IN KIND.
- MISSING TRAFFIC DELINEATOR. REPLACE IN KIND. SEE DETAIL 5 ON DWG. A12-A-503.

8 - STAINED/ VANDALIZED/ WORN OUT

- (8A) STAINED/ VANDALIZED SIGN. POWERWASH.
- STAINED/ VANDALIZED WALL. POWERWASH.
- STAINED CEILING TILE. REPLACE IN KIND.
- STAINED OR WORN OUT FLOORING. REPLACE IN KIND.
- STAINED/ VANDALIZED BOOTH. POWERWASH.
- STAINED/ VANDALIZED DOOR AND FRAME. POWERWASH AND REPAINT.

9 - MISCELLANEOUS

- WASP OR BIRD NEST. REMOVE AS REQUIRED.
- PLANT ENCROACHMENT. REMOVE AS REQUIRED.

	GF =		ett Fleming/Parsons NT VENTURE
9	Graham Lane Thomas	DOCUMENTS WERE	RTIFICATION: I HEREBY CERTIFY THAT THESE PREPARED OR APPROVED BY ME, AND THAT I D ARCHITECT UNDER THE LAWS OF THE F VIRGINIA."
	Lic. No. 0401015717	LICENSE No.	0401015717
	01 25 2018	EXPIRATION DATE:	06/30/2019
	RCHITE		- VA Regulations 18VAC10-20-760

	REFERENCE DRAWINGS		REVISIONS		REVISIONS	
)	NUMBER	TITLE	DATE	NUM	DESCRIPTION	
DESIGNED A.KATIGBAK 01/2018 DATE			01/25/2018	0	FINAL SUBMITTAL	
A 1/A TIODAI/ 04/0040			05/15/2018	1	AMENDMENT #2	
DRAWN A.KATIGBAK 01/2018 DATE						
CHECKED G.THOMAS 01/2018						
DATE						

WASHINGTON METROPOLITAN AREA TRANSIT AUTHORITY

OFFICE OF DESIGN AND CONSTRUCTION > IRPG - FIXED FACILITIES

APPROVED	01/25/2018	APPROVED	01/25/2018
JOHN PURDY	DATE	GRAHAM THOMAS	DATE
ENGINEERING MANAGER		ARCHITECT OF SECORD	

REHABILITATION OF PARKING GARAGES	
K06 - WEST FALLS CHURCH PARKING GARAGE	-
ARCHITECTURAL KEYNOTES BY DEFICIENCY	

NO.	CONTRACT NO.	SCALE	DRAWING NO.	SHEET NO.
<i>I</i> 1301	FQ18064	AS NOTED	K06-A-002	341 of 503











