Please see the following list of bid quantities. It shows the quantities added up from the plan pages vs the quantities provided on the bid form, by

Item	Garage Name	From plan Page	From Bid form	Resolution
2	White flint	4,240	21,289	Quantity in drawing is correct. We will revise the bid form with AM2.
3	New Carrolton	32,375	32,441	Quantity in drawing 32,375 is correct. We will revise the bid form with AM2.
3	Vienna	28,800	43,212	Plan drawing S-105 is updated.
7	Largo North	8,699	11,160	Quantity in drawing is 7,438, not 8,699. We will revise the bid form with AM2.
7	Vienna	567	554	Quantity in drawing is correct. We will revise the bid form with AM2.
8	New Carrolton	2,758	1,964	Quantity in drawing 2,758 is correct. We will revise the bid form with AM2.
8	Largo North	11,160	11,257	Quantity in drawing 11,160 is correct. We will revise the bid form with AM2.
12	Largo North	36	27	Quantity in drawing is 27, not 36. This quantity matches the bid form.
13	Largo North	810	585	Quantity in drawing is 585, not 810. This quantity matches the bid form.
14	Largo South	60	70	Quantity in drawing is correct. We will revise the bid form with AM2.
15	Largo North	568	30	Quantity in drawing 568 is correct. We will revise the bid form with AM2.
17	Largo North	21	10	Quantity in drawing is 11, not 21. We will revise the bid form with AM2.
18	Largo North	23	21	Quantity in drawing is 21, not 23. This quantity matches the bid form.
23	Vienna	156,000	153,600	Quantity in drawing is correct. We will revise the bid form with AM2.
23	White flint	77,142	71,581	Quantity in drawing is correct. We will revise the bid form with AM2.
24	West Falls Church	0	8	Both drawing and bid form show the quantity is 0. The quantity in bid form is not 8.
25	West Falls Church	8	0	Both drawing and bid form show the quantity is 8. The quantity in bid form is not 0.
27	Largo North	422	418	Quantity in drawing is 418, not 422. This quantity matches the bid form.
28	Largo South	52	13	Quantity in drawing is correct. We will revise the bid form with AM2.
29	Largo North	12	6	Quantity in drawing 12 is correct. We will revise the bid form with AM2.
30	New Carrolton	159	570	Quantity in drawing 159 is correct. We will revise the bid form with AM2.
36	Largo North	307	283	Quantity in drawing is 283, not 307. This quantity matches the bid form.
40	Largo North	7,140	6,000	Quantity in drawing is 6,000, not 7,140. This quantity matches the bid form.
1B	New Carrolton	4	7	Quantity in drawings is correct. Bid form to be revised.
1C	Largo South	16	15	Quantity in drawings is correct. Bid form to be revised.
1E	White flint	21	0	Quantity in drawings is correct. Bid form to be revised.
1G	White flint	20	17	Quantity in drawings is correct. Bid form to be revised.
1H	New Carrolton	7	3	Quantity in drawings is correct. Bid form to be revised.

11	Largo South	0	1	Quantity in drawings is correct. Bid form to be revised.
1J	Largo South	0	1	Quantity in drawings is correct. Bid form to be revised.
1J	Largo North	4	5	Quantity in drawings is correct. Bid form to be revised.
2G	Largo North	2	3	Quantity in drawings is correct. Bid form to be revised.
2G	White flint	8	0	Quantity in drawings is correct. Bid form to be revised.
3B	Largo South	7	10	Quantity in drawings is correct. Bid form to be revised.
4A	Largo South	24	0	Quantity in drawings is correct. Bid form to be revised.
4A	White flint	16	35	Quantity in drawings is correct. Bid form to be revised.
4B	New Carrolton	0	1	Quantity in drawings is correct. Bid form to be revised.
5A	West Falls Church	12	10	All pavement markings are to be replaced as LS item
5A	New Carrolton	1	0	All pavement markings are to be replaced as LS item
5B	West Falls Church	10	20	All pavement markings are to be replaced as LS item
5F	White flint	15	13	All pavement markings are to be replaced as LS item
5G	White flint	220	217	All pavement markings are to be replaced as LS item
6A	New Carrolton	107	115	Quantity in drawings is 107.5. Quantity in drawings is correct.
6A	Largo North	28	108	Quantity in drawings is correct. Bid form to be revised.
7A	Largo South	8	6	Quantity in drawings is correct. Bid form to be revised.
7B	West Falls Church	1	0	Quantity in drawings is correct. Bid form to be revised.
7C	New Carrolton	1	2	Quantity in drawings is correct. Bid form to be revised.
7H	White flint	6	0	Quantity in drawings is correct. Bid form to be revised.
7H	New Carrolton	3	2	Quantity in drawings is correct. Bid form to be revised.
7H	Largo South	4	1	Quantity in drawings is correct. Bid form to be revised.
8A	White flint	1	2	Quantity in drawings is correct. Bid form to be revised.
8A	New Carrolton	2	3	Quantity in drawings is 2. Bid form to be revised
8A	Largo South	3	4	Quantity in drawings is correct. Bid form to be revised.
8B	Largo South	31	6	Quantity in drawings is correct. Bid form to be revised.
8C	Largo South	12	31	Quantity in drawings is correct. Bid form to be revised.
8E	West Falls Church	0	2	Quantity in drawings is correct. Bid form to be revised.
8F	West Falls Church	2	0	Quantity in drawings is correct. Bid form to be revised.
9A	Largo South	4	0	Quantity in drawings is correct. Bid form to be revised.
IJ	Largo North	4	5	Duplicate of row 36
IJ	Largo South	0	1	Duplicate of row 35